






PRODUCT NAME: BEADBOARD DRYING RACK LARGE
ITEM NUMBER: MI442 LRG
DIMENSIONS OF ITEM ASSEMBLED: 46" X 2 3/8" X 42 1/4"H




| Ltr. | Qty. | Hardware Included | |
|------|------|---|----------------|
| A | 3 |  | Wall Anchor |
| B | 3 |  | Tap Head Screw |
| C | 1 |  | Mounting Cleat |

Required Tools:
Phillips Screwdriver
Drill
Level

| Ltr. | Qty. | Components |
|------|------|--|
| D | 1 |  <p>Large Drying Rack</p> |

STEP 1: Determine exact location of Drying Rack on wall. Using a level, place Mounting Cleat (C) in desired location and use a pencil to mark three holes. NOTE: At least two (preferably all) screws must be driven into a stud. Use a drill to create small holes in drywall and insert an Anchor (A) into the open drywall holes, but **NO hole or anchor over a stud**.

STEP 2: Align holes in Mounting Cleat with Anchors and stud(s) and use Tap Head Screw (B) to secure cleat to wall. Firmly tighten.



Step 3: Gently lift and hang Drying Rack on Mounting Cleat (C) by hooks mounted on each end of the Drying Rack.

