






PRODUCT NAME: BEADBOARD DRYING RACK MEDIUM  
ITEM NUMBER: MI442 MED  
DIMENSIONS OF ITEM ASSEMBLED: 23" X 2 3/8" X 42 1/4"H




Ltr.	Qty.	Hardware Included	
A	2		Plastic Anchor
B	2		Tap Head Screw
C	1		Mounting Cleat

REQUIRED TOOLS:  
Phillips Screwdriver  
Level  
Drill

Ltr.	Qty.	Components
D	1	 <p>(D) Drying Rack Medium Qty.1 pc.</p>

STEP 1: Determine exact location of Drying Rack on wall. Using a level, place Mounting Cleat (C) in desired location and use a pencil to mark two holes. NOTE: At least one (preferably both) screws must be driven into a stud. Use a drill to create small holes in drywall and insert an Anchor (A) into the open drywall holes, **but no hole or anchor over a stud.**

STEP 2: Align holes in Mounting Cleat with Anchors and stud(s) and use Tap Head Screw (B) to secure cleat to wall. Firmly tighten.



Step 3: Gently lift and hang Drying Rack on Mounting Cleat (C) by hooks mounted on each end of the Drying Rack.

